Q-265R1

SVE BULLETIN

SPECIAL VEHICLE ENGINEERING – BODY BUILDERS ADVISORY SERVICE

E-Mail via Website: www.FordBBAS.com (click "Contact Us")

Toll-free: (877) 840-4338

2017-22MY F-SERIES PICKUP ONLY – BOX REMOVAL WITH BLIND SPOT INFORMATION SYSTEM (BLIS)

REVISION	UPDATE	REVISION DATE
Q-265R1	ADDED MODEL YEAR CUTOFF & MINOR FORMATTING REVISIONS	08FEB2023
Q-265	INITIAL RELEASE	09NOV2022

MODEL(S) AFFECTED:
2017 thru 2022 MODEL YEAR (MY) F-Super Duty – F250/F350 Pickups used for box removal

ISSUE / DESCRIPTION:
Some 2017 through 2022MY F-Super Duty vehicles equipped with BLIS that have had the pickup box removed for upfitter modification may exhibit a BLIS warning message in the message center.

Solution:
To correct this concern, use Integrated Diagnostic System (IDS) service tool version 104.01 or later to configure the BLIS system. These settings can be found under toolbox > module programming > programmable parameters > warning lamps and chimes and must be adjusted in multiple modules.

BLIS capability is disabled

BLIS option is not offered on Pickup box delete

Not recommended for box removal; sensors are in the factory tail lamps being removed

Reference SSM 46387 for Dealer Service Procedure

Refer to the Body Builder Layout Book for additional guidelines and recommendations. If you have any questions, please contact the Ford Body Builders Advisory Service as shown in the header of this bulletin.